

FIGURE 1




FIGURE 2




FIGURE 3




FIGURE 4




FIGURE 5




FIGURE 6

FAT 500	
0000	0000
0001	FFF7
0002	0000
...	
000F	0100
0010	0100
...	
FFFE	0100
FFFF	0000

FIGURE 7

